

Bas. start date	Basic fin. date	Sort field	Description
03/10/2013	03/10/2013	TM02	TM02 Roller Clamp Pivot Bushes Worn
03/10/2013	03/10/2013	TM02	TM02 Rear horn not working
05/10/2013	05/10/2013	TM02	TM02 W/HEAD TYNE RETAINING BOLTS SPARES
05/10/2013	21/06/2014	TM02	TM02 - FIT NEW ROD/CLEVIS TO CYLINDER
05/10/2013	19/07/2014	TM02	TM02 Replace lining trolley beam TECO
08/10/2013	08/10/2013	TM02	12M Stat Insp TM02 Fire Equipment
17/10/2013	17/10/2013	TM02	Repair TM02 servo valves
22/10/2013	16/12/2013	TM02	TM02 Engine breakdown on mainline SES
31/10/2013	31/10/2013	TM02	TM02 Replace worn tynes
11/11/2013	11/11/2013	TM02	TM02 Bogie support cylinder leaking
11/11/2013	11/11/2013	TM02	TM02 H-frame cylinder requires overhaul
08/12/2013	08/12/2013	TM02	TM02/5 roller clamps to be rebuilt
27/12/2013	07/04/2014	TM02	TM02 ENGINE FAILURE TECO
30/12/2013	30/12/2013	TM02	3M Stat Insp TM02 Generator
30/12/2013	30/12/2013	TM02	3M Stat Insp TM02 RCD Test
08/01/2014	08/01/2014	TM02	12M Stat Insp TM02 Switch Boards
12/01/2014	12/01/2014	TM02	TM02 Change engine oil and coolant
14/01/2014	14/01/2014	TM02	TM02 Steel braided hose is leaking
20/01/2014	20/01/2014	TM02	TM02 Replace wiper arms on rear motor
20/01/2014	20/01/2014	TM02	3M Stat Insp TM02 Test & Tag
20/01/2014	20/01/2014	TM02	32W Elec Svce TM02
20/01/2014	20/01/2014	TM02	3M Stat Insp TM02 Thermo
20/01/2014	20/01/2014	TM02	3M Stat Insp TM02 E-Stops
24/01/2014	24/01/2014	TM02	TM02 6M Fire Supression Inspect
02/02/2014	03/02/2014	TM02	TM02 Engine Oil found In Coolant
08/02/2014	08/02/2014	TM02	TM02 Broken guide column bolt L/H W/Head
13/02/2014	13/02/2014	TM02	NOT NEEDED/TECHO
23/02/2014	23/02/2014	TM02	TM02 Fan belts came off & coolant spilt
25/02/2014	25/02/2014	TM02	TM02 Fan shroud broken needs repair
27/02/2014	27/02/2014	TM02	TM02 Roller Clamp Housings
27/02/2014	27/02/2014	TM02	TM02 Sat slew locking pin
27/02/2014	27/02/2014	TM02	8W Mech Svce TM02
27/02/2014	27/02/2014	TM02	32W Mech Insp TM02
27/02/2014	27/02/2014	TM02	8W Elec Svce TM02
28/02/2014	28/02/2014	TM02	TM02 lifting unit lock solenoid valve
28/02/2014	28/02/2014	TM02	TM02 Work Head Stauff Clump U/S
03/03/2014	03/03/2014	TM02	TM02 Replace High Pressure Filter Housin
08/03/2014	08/03/2014	TM02	TM02 oil leak
19/03/2014	19/03/2014	TM02	3M Stat Insp TM02 Thermo
19/03/2014	19/03/2014	TM02	TM02 Fuel Shut Off Soleniod Faulty
20/03/2014	20/03/2014	TM02	3M Stat Insp TM02 Generator
20/03/2014	20/03/2014	TM02	3M Stat Insp TM02 RCD Test
20/03/2014	20/03/2014	TM02	3M Stat Insp TM02 E-Stops
21/03/2014	21/03/2014	TM02	3M Stat Insp TM02 Test & Tag
01/04/2014	01/04/2014	TM02	8W Elec Svce TM02
08/04/2014	08/04/2014	TM02	TM02 Broken Spacer Cylinder
23/04/2014	23/04/2014	TM02	8W Mech Svce TM02
23/04/2014	23/04/2014	TM02	8W Mech Insp TM02

23/04/2014	24/04/2014	TM02	16W Mech Svce TM02
24/04/2014	24/04/2014	TM02	TM02 Cabin Windows Need Replace TECO
24/04/2014	24/04/2014	TM02	8W Mech Insp TM02
24/04/2014	25/04/2014	TM02	32W Mech Svce TM02
24/04/2014	24/04/2014	TM02	8W Elec Svce TM02
25/04/2014	25/04/2014	TM02	TM02 Broken fitting in fluro light TECO
25/04/2014	25/04/2014	TM02	TM02 LHS Work Light Missing At Work Head
25/04/2014	25/04/2014	TM02	TM02 Repair Weeping oil from Axle 3
25/04/2014	25/04/2014	TM02	8W Mech Insp TM02
25/04/2014	25/04/2014	TM02	12M Stat Insp TM02 Fire Equipment TECO
26/04/2014	26/04/2014	TM02	TM02 Work head hyd manifold brackets
26/04/2014	26/04/2014	TM02	TM02 potenetiometers for repairs TECO
26/04/2014	26/04/2014	TM02	TM02 Check and repair machine proxys
27/04/2014	27/04/2014	TM02	TM02 INSPECT HOOK CYLINDERS
27/04/2014	27/04/2014	TM02	TM02 front Bogie Brake Retainer
27/04/2014	27/04/2014	TM02	TM02-PRON-WKHS-GREASE PLATE BROKEN
27/04/2014	27/04/2014	TM02	TM02 Replace Oil Cooler Gaskets
27/04/2014	27/04/2014	TM02	TM02 Fit Sleeve over Lifting Cords
27/04/2014	27/04/2014	TM02	TM02 Replace fan belts
27/04/2014	27/04/2014	TM02	TM02 Replace Lining cord pneumatic valve
28/04/2014	28/04/2014	TM02	TM02 trailer brakes to be rebushed TECO
28/04/2014	28/04/2014	TM02	TM02 R/Hand Hook In Out Cylinder
29/04/2014	29/04/2014	TM02	TM02 Scope Alternator Pulleys and Belts
29/04/2014	29/04/2014	TM02	TM02 Lift and lining calibrations
29/04/2014	29/04/2014	TM02	TM02 Calibrate hooks
29/04/2014	29/04/2014	TM02	TM02 Front Ops Cab Wiper Blades U/S
30/04/2014	30/04/2014	TM02	TM02 Coolant leak at RH cylinder head
09/05/2014	09/05/2014	TM02	TM02 Broken snail pot wire on workhead
20/05/2014	03/06/2014	TM02	TM02 Derailed at Garden back track
21/05/2014	21/05/2014	TM02	TM02 L/H hook working eractic
21/05/2014	22/05/2014	TM02	TM02 Derailed at Garden back track
22/05/2014	23/05/2014	TM02	TM02 Derailed at Garden back track
27/05/2014	27/05/2014	TM02	TM02 derailment at Garden
05/06/2014	06/06/2014	TM02	TM02 Travel Garden to TMWS
11/06/2014	11/06/2014	TM02	Inspect TM02 brake
14/06/2014	14/06/2014	TM02	TM02 Portable Welder Requires Test & Tag
18/06/2014	18/06/2014	TM02	TM02 Wiper Arm Missing on Rear Cab
18/06/2014	18/06/2014	TM02	TM02 Replace Alternator Pulleys & Belts
18/06/2014	18/06/2014	TM02	3M Stat Insp TM02 E-Stops
19/06/2014	19/06/2014	TM02	8W Elec Svce TM02
19/06/2014	19/06/2014	TM02	8W Mech Insp TM02
20/06/2014	20/06/2014	TM02	TM02 Repair Axle 3 proximity cables
20/06/2014	20/06/2014	TM02	8W Mech Svce TM02
21/06/2014	21/06/2014	TM02	TM02 B Trolley Needs Additional Rollers
21/06/2014	21/06/2014	TM02	TM02 Wheel support cylinder damaged seal
21/06/2014	21/06/2014	TM02	TM02 Measuring Trolley Limit Switches
22/06/2014	22/06/2014	TM02	TM02 Swivel cylinders need resealing
22/06/2014	22/06/2014	TM02	TM02 Hydraulic Leak Work Drive Motor
22/06/2014	22/06/2014	TM02	TM02 3rd arm extension cylinder reseal

22/06/2014	22/06/2014	TM02	TM02 Back end alternator guard damaged
22/06/2014	22/06/2014	TM02	3M Stat Insp TM02 Test & Tag
22/06/2014	22/06/2014	TM02	3M Stat Insp TM02 Generator
22/06/2014	22/06/2014	TM02	3M Stat Insp TM02 Thermo
22/06/2014	22/06/2014	TM02	3M Stat Insp TM02 RCD Test
22/06/2014	06/07/2014	TM02	TM02 Investigate disconnected MEN
22/06/2014	22/06/2014	TM02	TM02 MEN disconnected on generator
24/06/2014	24/06/2014	TM02	TM02 W/Head Side Shift Valves leaking
25/06/2014	25/06/2014	TM02	TM02 WorkDrive Diff 4 repair
25/06/2014	25/06/2014	TM02	TM02 Reduction G/Box Oil Sample
25/06/2014	25/06/2014	TM02	TM02 ZF Trans Oil Re-Sample
25/06/2014	25/06/2014	TM02	TM02 Fit Drum Holders To Match Trailer
27/06/2014	15/07/2014	TM02	TM02 Derailment Repairs
28/06/2014	28/06/2014	TM02	TM04 Check MEN and generator connections
30/06/2014	30/06/2014	TM02	TM02 Check Engine Oil sample Status
05/07/2014	05/07/2014	TM02	Repair TM02 Damaged Rear Cab Aircon
07/07/2014	07/07/2014	TM02	TM02 Check and repair hyd leaks on mach
15/07/2014	15/07/2014	TM02	TM02 WorkHead Carry Height Fault (op sup
15/07/2014	15/07/2014	TM02	TM02 Snail pot hook working erratic (Op
18/07/2014	18/07/2014	TM02	TM02 Replace B trolley lifting cylinders
18/07/2014	18/07/2014	TM02	TM02 Exhaust Wrapping Needs Replacing
20/07/2014	20/07/2014	TM02	TM02 Install W/head Oil Reservoir Cap
21/07/2014	23/07/2014	TM02	TM02 Machine repairs from derail TECO
21/07/2014	21/07/2014	TM02	TM02 Repair OIL PRESSURE GAUGES
29/07/2014	29/07/2014	TM02	TM02 W/Head Lift Cylinder Pins And Bush
29/07/2014	29/07/2014	TM02	TM02 Scope/Design layout for desktop com
30/07/2014	30/07/2014	TM02	Collect SAP history of TM02 maintenance
06/08/2014	30/09/2014	TM02	TM02 Noisy Flow Divider TECO
06/08/2014	06/08/2014	TM02	TM02 L/H Front Pneumatic Regulator repla
07/08/2014	07/08/2014	TM02	TM02 Repair Air Dryer Module
10/08/2014	10/08/2014	TM02	TM02 Break Beam Cracked
11/08/2014	11/08/2014	TM02	TM02 Replace front brake beam
11/08/2014	11/08/2014	TM02	1Y Sfty Insp Trauma Kit TM02
11/08/2014	11/08/2014	TM02	TM02 SIGHT GLASS LEAKING ON OIL FEEDERS
12/08/2014	12/08/2014	TM02	TM02 HYDRAULIC VALVE LOCKS ORINGS WORN
13/08/2014	13/08/2014	TM02	TM02 Cracked mount on sliding TECO SES
13/08/2014	13/08/2014	TM02	TM02 Replace terminal block on generator
13/08/2014	13/08/2014	TM02	TM02 Replace Oil Pressure Sender
13/08/2014	13/08/2014	TM02	16W Oper Svce Inbound TM02
14/08/2014	15/08/2014	TM02	64W Elec Svce TM02 TECO
14/08/2014	16/08/2014	TM02	64W Mech Svce TM02 TECO
14/08/2014	14/08/2014	TM02	6M Stat Insp TM02 Fire Equipment
15/08/2014	15/08/2014	TM02	TMWS- Review brake testing procedures
15/08/2014	15/08/2014	TM02	TMWS- Review machine stabling procedures
16/08/2014	16/08/2014	TM02	64W Mech Insp TM02
18/08/2014	19/08/2014	TM02	TM02 Commissioning WK34 TECO
18/08/2014	18/08/2014	TM02	TM02 Pinch Point At Access Ladder
19/08/2014	19/08/2014	TM02	TM02 Workhead centering not working
19/08/2014	19/08/2014	TM02	TM02 M.E.N. Label Install

19/08/2014	19/08/2014	TM02	16W Oper Svce Out-bound TM02
19/08/2014	19/08/2014	TM02	TM02 Engine Radiator Core And Machine
21/08/2014	21/08/2014	TM02	TM02 HYD HOSES DAMAGE
21/08/2014	21/08/2014	TM02	TM02 FIT HAZARD CABNET TO MACHINE
21/08/2014	21/08/2014	TM02	TM02 E stop buttons faded
22/08/2014	22/08/2014	TM02	TM02 Genset E stop lockable
22/08/2014	22/08/2014	TM02	TM02 Pressure Washing Machine
29/08/2014	29/08/2014	TM02	Apply Just Culture to TM02 Operator
03/09/2014	03/09/2014	TM02	TM02 Air dryer change out
03/09/2014	03/09/2014	TM02	TM02 Replace air dryer module
04/09/2014	04/09/2014	TM02	TM02 change alternator pulley and belts
08/09/2014	10/09/2014	TM02	TM02 calibration
10/09/2014	10/09/2014	TM02	TM02 compressor needs changing out
12/09/2014	12/09/2014	TM02	TM02 No work drive
12/09/2014	12/09/2014	TM02	TM02 Rear trolley not contact feeler rod
12/09/2014	12/09/2014	TM02	TM02 Linning Trolley Not Referencing
13/09/2014	13/09/2014	TM02	TM02 Calibration
13/09/2014	13/09/2014	TM02	TM02 Low cut in on system air pressure
16/09/2014	16/09/2014	TM02	TM02 Brakes Require Adjusting
16/09/2014	16/09/2014	TM02	TM02 Rear Cab Air Horn
16/09/2014	16/09/2014	TM02	TM02 Brake Limit Switch Needs Adjusting
19/09/2014	19/09/2014	TM02	TM02 Left hand hook pot is erratic.
26/09/2014	26/09/2014	TM02	TMWS- Review brake maintenance strategy
11/10/2014	11/10/2014	TM02	TM02 L/H FRONT INN TYNE CYLINDER Replace
11/10/2014	11/10/2014	TM02	TM02 Replace Damaged Solenoid Plugs
11/10/2014	11/10/2014	TM02	TM02 Replace PLC Battery
11/10/2014	11/10/2014	TM02	TM02 Diffs Triceptor Breathers Install
11/10/2014	11/10/2014	TM02	3M Stat Insp TM02 Generator
11/10/2014	11/10/2014	TM02	3M Stat Insp TM02 Thermo
11/10/2014	11/10/2014	TM02	3M Stat Insp TM02 E-Stops
11/10/2014	11/10/2014	TM02	8W Mech Svce TM02
11/10/2014	11/10/2014	TM02	1Y Stat Test Fixed RCD Injection TM02
11/10/2014	11/10/2014	TM02	6M Stat Test Fixed RCD Button TM02
12/10/2014	12/10/2014	TM02	TM02 LIFTING TROLLEY S/SHIFT CYL Replace
12/10/2014	12/10/2014	TM02	TM02 Replace Cab Light covers
12/10/2014	12/10/2014	TM02	8W Elec Svce TM02
12/10/2014	12/10/2014	TM02	8W Mech Insp TM02
12/10/2014	12/10/2014	TM02	TM02 No index during work
13/10/2014	14/10/2014	TM02	TM02 L/H REAR OUTER SQUEEZE CYL Replace
13/10/2014	13/10/2014	TM02	TM02 Rear Alternator due for changeout
13/10/2014	13/10/2014	TM02	TM02 RPL outer head extension hyd valve
13/10/2014	13/10/2014	TM02	3M Stat Insp TM02 Test & Tag
13/10/2014	13/10/2014	TM02	1Y Sfty Insp Guarding & Handrails TM02
13/10/2014	13/10/2014	TM02	1Y Stat Insp Safety Signs TM02
15/10/2014	15/10/2014	TM02	TM02 Low fuel alarm
24/10/2014	24/10/2014	TM02	TM02 RHS Inner Head Faulty Snail Pot
24/10/2014	24/10/2014	TM02	TM02 Broken Knuckle On Lock Cylinder
29/10/2014	12/11/2014	TM02	TM02 Convert park brake actuation
29/10/2014	05/11/2014	TM02	2W Oper Insp Tamper TM02

29/10/2014	05/11/2014	TM02	4W Oper Insp Tamper TM02
01/11/2014	01/11/2014	TM02	TM02 Rear Beacon Not Illuminated
01/11/2014	01/11/2014	TM02	TM02 Front cab axle 3 indication fault
02/11/2014	02/11/2014	TM02	TM02 Lining versine transmitter rods
03/11/2014	03/11/2014	TM02	TM02 Replace Worklight on RHS (op sup)
03/11/2014	03/11/2014	TM02	TM02 R/Work Head Manifold Leaking (op su
12/11/2014	12/11/2014	TM02	TM02 W/Head Lift Cylinder Clevis Loose
12/11/2014	19/11/2014	TM02	2W Oper Insp Tamper TM02
12/11/2014	19/11/2014	TM02	4W Oper Insp Tamper TM02
17/11/2014	17/11/2014	TM02	16W Oper Svce Inbound Tamper TM02
19/11/2014	26/11/2014	TM02	2W Oper Insp Tamper TM02
19/11/2014	26/11/2014	TM02	4W Oper Insp Tamper TM02
24/11/2014	24/11/2014	TM02	rear cab air horn unsatisfactory
24/11/2014	24/11/2014	TM02	TM02 Electrical repairs as listed
24/11/2014	24/11/2014	TM02	TM02 blown hyd hose L/H work head
24/11/2014	24/11/2014	TM02	TM02 Repair broken locks on head slew
25/11/2014	25/11/2014	TM02	TM02 Exhaust Maniold Leaking
26/11/2014	03/12/2014	TM02	2W Oper Insp Tamper TM02
26/11/2014	03/12/2014	TM02	4W Oper Insp Tamper TM02
03/12/2014	03/12/2014	TM02	16W Oper Svce Inbound Tamper TM02
03/12/2014	11/12/2014	TM02	2W Oper Insp Tamper TM02
03/12/2014	11/12/2014	TM02	4W Oper Insp Tamper TM02
04/12/2014	05/12/2014	TM02	TM02 Noisy Return Valve Fan Motor
04/12/2014	05/12/2014	TM02	16W Mech Svce TM02
04/12/2014	04/12/2014	TM02	8W Elec Svce TM02
04/12/2014	04/12/2014	TM02	TM02 Broken workhead lock
05/12/2014	05/12/2014	TM02	TM02 Intermittent Fault With C/B
05/12/2014	06/12/2014	TM02	TM02 Top alternator faulty to be replace
05/12/2014	05/12/2014	TM02	TM02 weld up hook ends on lifting hooks
05/12/2014	05/12/2014	TM02	TM02 RH Lining cylinder is bent
05/12/2014	05/12/2014	TM02	Scope Vigilance Light/Buzzer Fault
05/12/2014	05/12/2014	TM02	12M Stat Insp TM02 Fire Equipment**SES**
05/12/2014	05/12/2014	TM02	TM02 Replace inner left roller clamp
06/12/2014	06/12/2014	TM02	48W Sfty Insp Pressure Vessel TM02
07/12/2014	07/12/2014	TM02	TM02 - New toolbox install
07/12/2014	07/12/2014	TM02	TM02 LH Inner Front Squeeze CYL Leaking
07/12/2014	07/12/2014	TM02	8W Mech Insp TM02
07/12/2014	07/12/2014	TM02	2Y Stat Insp Earthing Systems TM02
08/12/2014	08/12/2014	TM02	TM02 replace Lifting Hooks bushes
08/12/2014	08/12/2014	TM02	TM02 Replace check valve at air dryer
08/12/2014	08/12/2014	TM02	TMO2 Diesel Tank Fire Extinguisher Sign
09/12/2014	09/12/2014	TM02	TM02 Change Hyd Pressure Filter
09/12/2014	09/12/2014	TM02	TM02 - Faded signs require replacement
09/12/2014	09/12/2014	TM02	TM02 replace HP servo filters
09/12/2014	09/12/2014	TM02	TM02 Repair Rear Alternator Gaurd
09/12/2014	09/12/2014	TM02	16W Oper Svce Outbound Tamper TM02
10/12/2014	17/12/2014	TM02	2W Oper Insp Tamper TM02
10/12/2014	17/12/2014	TM02	4W Oper Insp Tamper TM02
11/12/2014	11/12/2014	TM02	TM02 - FIT NEW BATTERY TO MAIN ENG

13/12/2014	13/12/2014	TM02	TM02 Faulty Fuel Soleniod
14/12/2014	14/12/2014	TM02	TM02 Left lift hook pot faulty
17/12/2014	24/12/2014	TM02	2W Oper Insp Tamper TM02
17/12/2014	24/12/2014	TM02	4W Oper Insp Tamper TM02
24/12/2014	31/12/2014	TM02	2W Oper Insp Tamper TM02
24/12/2014	31/12/2014	TM02	4W Oper Insp Tamper TM02
30/12/2014	30/12/2014	TM02	TM02 Incorrect pins in flaps
30/12/2014	30/12/2014	TM02	TM02 Hyd hose breakdown
31/12/2014	07/01/2015	TM02	2W Oper Insp Tamper TM02
31/12/2014	07/01/2015	TM02	4W Oper Insp Tamper TM02
01/01/2015	01/01/2015	TM02	6M Stat Insp TM02 Fire Equipment
03/01/2015	03/01/2015	TM02	3M Stat Insp TM02 Test & Tag
03/01/2015	03/01/2015	TM02	3M Stat Insp TM02 Generator
03/01/2015	03/01/2015	TM02	3M Stat Insp TM02 Thermo
03/01/2015	03/01/2015	TM02	3M Stat Insp TM02 E-Stops
04/01/2015	04/01/2015	TM02	12M Stat Insp TM02 Switch Boards
07/01/2015	14/01/2015	TM02	2W Oper Insp Tamper TM02
07/01/2015	14/01/2015	TM02	4W Oper Insp Tamper TM02
14/01/2015	21/01/2015	TM02	2W Oper Insp Tamper TM02
14/01/2015	21/01/2015	TM02	4W Oper Insp Tamper TM02
28/01/2015	01/02/2015	TM02	2W Oper Insp Tamper TM02
28/01/2015	01/02/2015	TM02	4W Oper Insp Tamper TM02
29/01/2015	29/01/2015	TM02	8W Elec Svce TM02
29/01/2015	29/01/2015	TM02	8W Mech Insp TM02
30/01/2015	30/01/2015	TM02	8W Mech Svce TM02
31/01/2015	31/01/2015	TM02	Replace TM02 exahust manifold
31/01/2015	31/01/2015	TM02	TM02 AIR SYSTEM OILER HOUSING (SPARE)
31/01/2015	31/01/2015	TM02	TM02 Rear cabin door handle worn
31/01/2015	31/01/2015	TM02	4Y Stat Repl PSV Pneumatic TM02
31/01/2015	31/01/2015	TM02	TM02 Engine Fan Broken
11/02/2015	18/02/2015	TM02	2W Oper Insp Tamper TM02
11/02/2015	18/02/2015	TM02	4W Oper Insp Tamper TM02
19/02/2015	19/02/2015	TM02	TM02 Fuel Solenoid failed
25/02/2015	04/03/2015	TM02	4W Oper Insp Tamper TM02
11/03/2015	18/03/2015	TM02	4W Oper Insp Tamper TM02
13/03/2015	13/03/2015	TM02	TM02 requires hour meter for work mode
14/03/2015	14/03/2015	TM02	TM02 requires wheel chock holders
14/03/2015	16/03/2015	TM02	TM02 Install New Coupler as per Drawing
14/03/2015	17/03/2015	TM02	2W Oper Insp Tamper TM02
24/03/2015	24/03/2015	TM02	TM02 air horn/ guage u/s **GR**
25/03/2015	01/04/2015	TM02	2W Oper Insp Tamper TM02
25/03/2015	01/04/2015	TM02	4W Oper Insp Tamper TM02
26/03/2015	26/03/2015	TM02	1Y Stat Insp Portable Fire Extg TM02
26/03/2015	26/03/2015	TM02	6M Stat Insp Fire Supp Track Mach TM02
26/03/2015	26/03/2015	TM02	3M Stat Insp TM02 Test & Tag
26/03/2015	26/03/2015	TM02	3M Stat Insp TM02 Generator
26/03/2015	26/03/2015	TM02	3M Stat Insp TM02 Thermo
26/03/2015	26/03/2015	TM02	3M Stat Insp TM02 E-Stops
26/03/2015	26/03/2015	TM02	TM02 No spare tynes onboard the machine

31/03/2015	31/03/2015	TM02	TM02 Lining versine wire damaged
07/04/2015	07/04/2015	TM02	6M Stat Test Fixed RCD Button TM02
15/04/2015	15/04/2015	TM02	TM02 Squeeze hydraulic hose failed
17/04/2015	18/04/2015	TM02	TM02 travel drive has failed
20/04/2015	20/04/2015	TM02	TM02 Rear alternator belt on main eng
20/04/2015	20/04/2015	TM02	TM02 park brake QR valve on axle 3&4 u/s
20/04/2015	20/04/2015	TM02	TM02 brake shoes worn
20/04/2015	20/04/2015	TM02	TM02 Low hydraulic oil
21/04/2015	21/04/2015	TM02	TM02 Scope for Hand Tamper Storage
23/04/2015	23/04/2015	TM02	Ops cabs windscreens leaking
25/04/2015	25/04/2015	TM02	TM02 fuel solenoid cable damaged
25/04/2015	25/04/2015	TM02	TM02 Flap Cylinder Solenoid Valve
25/04/2015	25/04/2015	TM02	32W Mech Insp TM02
25/04/2015	25/04/2015	TM02	16W Oper Svce Inbound Tamper TM02
26/04/2015	26/04/2015	TM02	32W Elec Svce TM02
26/04/2015	28/04/2015	TM02	32W Mech Svce TM02
27/04/2015	27/04/2015	TM02	TM02 Laser battery faulty
28/04/2015	28/04/2015	TM02	TM02 require guage replacement
28/04/2015	28/04/2015	TM02	3M Stat Test DB TM02
29/04/2015	02/05/2015	TM02	TM02 Starter Motor U/S
30/04/2015	20/07/2015	TM02	TM02 repalce Engine fan pulley
01/05/2015	01/05/2015	TM02	TM02 Excessive Play Lift Clamp Cylinder
02/05/2015	02/05/2015	TM02	TM02 SQUEEZE FLAP CLY PINS/BUSHES WORN
02/05/2015	02/05/2015	TM02	TM02 - OVERHAUL FLAP CYL AND PINS
03/05/2015	03/05/2015	TM02	TM02 Scope Flap Pins
04/05/2015	04/05/2015	TM02	16W Oper Svce Outbound Tamper TM02
07/05/2015	07/05/2015	TM02	TM02 Replace hydraulic return filters
08/05/2015	08/05/2015	TM02	Travel TM02 from Weeli
11/05/2015	11/05/2015	TM02	TM02 Control Labels Not Clear In Op Cab
11/05/2015	11/05/2015	TM02	TM02 has two cracked windows
13/05/2015	13/05/2015	TM02	TM02 Intermittent Lock Warning Fault
16/06/2015	16/06/2015	TM02	TM02 worn hyd hoses around heads
16/06/2015	16/06/2015	TM02	TM02 hand tamper storage
17/06/2015	17/06/2015	TM02	TM02 Replace OEM manual folders/drawings
01/07/2015	01/07/2015	TM02	3M Stat Insp TM02 Test & Tag
01/07/2015	01/07/2015	TM02	3M Stat Insp TM02 Generator
01/07/2015	01/07/2015	TM02	3M Stat Insp TM02 E-Stops
06/07/2015	06/07/2015	TM02	3M Stat Test DB TM02
15/07/2015	15/07/2015	TM02	TM02 - REPAIR LIFTING HOOKS
15/07/2015	15/07/2015	TM02	workhead hose needs replacing
15/07/2015	15/07/2015	TM02	TM02 No. 1 workhead height wrong
16/07/2015	17/07/2015	TM02	TM02 Service Wk29
17/07/2015	17/07/2015	TM02	8W Elec Svce TM02
17/07/2015	17/07/2015	TM02	8W Mech Insp TM02
17/07/2015	17/07/2015	TM02	24W Oper Svce Inbound Tamper TM02
18/07/2015	18/07/2015	TM02	TM02 Lift unit hooks to be caliibrated
18/07/2015	18/07/2015	TM02	TM02 Head Split Pneumatic Proxy Damaged
18/07/2015	18/07/2015	TM02	TM02 - INNER FLAP CYL U/S
18/07/2015	18/07/2015	TM02	TM02 Engine throttle actuator seized

18/07/2015	18/07/2015 TM02	8W Mech Svce TM02
18/07/2015	18/07/2015 TM02	12W Elec Svce TM02
18/07/2015	19/07/2015 TM02	12W Mech Svce TM02
19/07/2015	19/07/2015 TM02	TM02 work lights around heads upgrade
19/07/2015	19/07/2015 TM02	TM02 park brake Q/R valve axle 1&2 leak
19/07/2015	19/07/2015 TM02	TM02 Tripping breaker for work functions
20/07/2015	20/07/2015 TM02	TM02 Encoder not working
21/07/2015	21/07/2015 TM02	Replace hydraulic Damaged hydraulic line
25/07/2015	25/07/2015 TM02	24W Elect Oper Svce Outbound Tamper TM02
26/07/2015	26/07/2015 TM02	TM02 Erratic Hook height
26/07/2015	26/07/2015 TM02	24W Oper Mech Svce Outbound Tamper TM02
28/07/2015	28/07/2015 TM02	TM02 guide coloum clamp bolts
06/08/2015	06/08/2015 TM02	TM02 - GPS Hi-Rail Antenna Works
07/08/2015	07/08/2015 TM02	5Y Stat Insp Portable Fire Extg TM02
26/08/2015	26/08/2015 TM02	TM02 Refuel at Gidgi and scope works
04/09/2015	04/09/2015 TM02	TM02 snail pot wire to replace
07/09/2015	07/09/2015 TM02	1Y Sfty Insp Trauma Kit TM02
10/09/2015	11/09/2015 TM02	Travel TM02 From Chichester To 6Rd JBJ
10/09/2015	10/09/2015 TM02	6M Stat Insp Fire Supp Track Mach TM02
13/09/2015	13/09/2015 TM02	24W Oper Svce Inbound Tamper TM02
30/09/2015	30/09/2015 TM02	TM02 Rear VHF radio
08/10/2015	09/10/2015 TM02	TM02 Travel Sandhill to RSM workshop
09/10/2015	09/10/2015 TM02	3M Stat Test DB TM02
09/10/2015	09/10/2015 TM02	6M Stat Test Fixed RCD Button TM02
10/10/2015	10/10/2015 TM02	TM02 Replace Coolant Hoses/Clamps
10/10/2015	10/10/2015 TM02	TM02 Replace Fan Pulley
10/10/2015	10/10/2015 TM02	TM02 Broken windscreen wiper
10/10/2015	10/10/2015 TM02	3M Stat Insp TM02 Test & Tag
10/10/2015	10/10/2015 TM02	3M Stat Insp TM02 Generator
10/10/2015	10/10/2015 TM02	3M Stat Insp TM02 E-Stops
10/10/2015	10/10/2015 TM02	1Y Stat Test Fixed RCD Injection TM02
10/10/2015	10/10/2015 TM02	1Y Stat Insp Safety Signs TM02
10/10/2015	10/10/2015 TM02	TM02 Oil pressure gauge inaccurate
10/10/2015	10/10/2015 TM02	TM02 ALC not reading encoder distance
10/10/2015	10/10/2015 TM02	TM02 work head hoses damaged
10/10/2015	10/10/2015 TM02	TM02 Broken tyne in workhead no. 2
11/10/2015	11/10/2015 TM02	1Y Sfty Insp Guarding & Handrails TM02
11/10/2015	11/10/2015 TM02	48W Sfty Insp Pressure Vessel TM02
12/10/2015	12/10/2015 TM02	TM02 Tamping Head Lock Assembly
12/10/2015	12/10/2015 TM02	TM02 Rear cab air horn quiet
12/10/2015	13/10/2015 TM02	24W Mech Svce TM02
13/10/2015	13/10/2015 TM02	TM02 Oil Leak at Engine Covers
13/10/2015	13/10/2015 TM02	6M Stat Insp Portable Fire Extg TM02 ses
13/10/2015	13/10/2015 TM02	1Y Stat Insp Fire Supp Track Mach TM02 s
13/10/2015	13/10/2015 TM02	12W Elec Svce TM02
13/10/2015	14/10/2015 TM02	96W Elec Svce TM02
14/10/2015	14/10/2015 TM02	TM02 Replace Rear Bogie Brake Pads
14/10/2015	14/10/2015 TM02	TM02 Replace air hose on workhead 1
15/10/2015	15/10/2015 TM02	TM02 Transmission Leaking Oil

15/10/2015	15/10/2015	TM02	TM02 L/H outer head hyd manifold bracket
16/10/2015	16/10/2015	TM02	Rear Windscreen Leak ses
17/10/2015	17/10/2015	TM02	4Y Stat Repl PSV Hydraulic TM02
19/10/2015	19/10/2015	TM02	TM02 Oil leak at Air Compressor
20/10/2015	20/10/2015	TM02	TM02 Rear Alternator Gaurd Cracked
02/11/2015	02/11/2015	TM02	TM02 - R/H WORKHEAD HOSE C/O
16/11/2015	16/11/2015	TM02	Tamping Tynes
29/11/2015	29/11/2015	TM02	1Y Inspection PSV Hydraulic TM02
30/11/2015	30/11/2015	TM02	TM02 replace broken inner & outer tynes
14/12/2015	17/12/2015	TM02	2W Oper Insp Tamper TM02
24/12/2015	24/12/2015	TM02	TM02 RCD/CB Damaged Handle Lock
29/12/2015	29/12/2015	TM02	TM02 Travel JBJ to RSM workshop
01/01/2016	02/01/2016	TM02	12W Mech Svce TM02
02/01/2016	02/01/2016	TM02	TM02 Broken squeeze flap
02/01/2016	02/01/2016	TM02	12W Elec Svce TM02
02/01/2016	02/01/2016	TM02	6M Stat Insp Portable Fire Extg TM02
03/01/2016	03/01/2016	TM02	TM02 Replace workhead hoses
03/01/2016	03/01/2016	TM02	TM02 Coolant Leak On Air Compressor
04/01/2016	04/01/2016	TM02	3M Stat Test DB TM02
05/01/2016	05/01/2016	TM02	TM02 Upgrade Work Lights
05/01/2016	05/01/2016	TM02	3M Stat Insp TM02 E-Stops
06/01/2016	06/01/2016	TM02	3M Stat Insp TM02 Test & Tag
06/01/2016	06/01/2016	TM02	3M Stat Insp TM02 Generator
07/01/2016	07/01/2016	TM02	TM02 Hyd Cooling valve coil faulty
07/01/2016	07/01/2016	TM02	TM02 Daily Inspections
08/01/2016	08/01/2016	TM02	TM02 Buzzer in rear cab broken
13/01/2016	13/01/2016	TM02	3M Stat Test Welder TM02
07/02/2016	07/02/2016	TM02	TM02 Oil Pressure Sender Faulty
07/02/2016	07/02/2016	TM02	TM02 Front right tail light not working
07/02/2016	07/02/2016	TM02	TM02 faded safety signs
07/02/2016	07/02/2016	TM02	TM02 Replace Left Lifting Unit Hose
13/02/2016	13/02/2016	TM02	TM02 Rear Trolley Lock Cylinders
14/02/2016	14/02/2016	TM02	TM02 C Trolley Lock Actuators Incorrect
14/02/2016	14/02/2016	TM02	TM02 Replace Pnuematic System Drawing
20/02/2016	20/02/2016	TM02	Daily Inspection TM02
26/03/2016	26/03/2016	TM02	TM02 Replace lifting unit roller bushes
26/03/2016	28/03/2016	TM02	48W Mech Svce TM02
27/03/2016	27/03/2016	TM02	TM02 hooks on lifting unit worn
27/03/2016	27/03/2016	TM02	TM02 Air compressor dripping oil
28/03/2016	28/03/2016	TM02	TM02 Windows require tinting *SES*
28/03/2016	28/03/2016	TM02	TM02 Reseal workhead split cylinders
28/03/2016	28/03/2016	TM02	TM02 B Trolley Lock Proxy Cable Damaged
28/03/2016	28/03/2016	TM02	TM02 Front cab door opens on its own
28/03/2016	28/03/2016	TM02	TM02 Broken Wiper
28/03/2016	28/03/2016	TM02	TM02 Feeler Rods PMI Inspect
29/03/2016	29/03/2016	TM02	TM02 Replace Front Cab Tail Lights
29/03/2016	29/03/2016	TM02	Tamper 2 ALC Sync Button Sticking on
29/03/2016	29/03/2016	TM02	3M Stat Insp TM02 E-Stops
30/03/2016	30/03/2016	TM02	TM02 - L/H LIFTING CLAMP TOP BUSH WORN

30/03/2016	30/03/2016	TM02	TM02 Roller Clamp Cylinder Leaking
30/03/2016	30/03/2016	TM02	TM02 high temp
30/03/2016	30/03/2016	TM02	3M Stat Insp TM02 Test & Tag
30/03/2016	30/03/2016	TM02	3M Stat Insp TM02 Generator
31/03/2016	31/03/2016	TM02	TM02 Wheel Chocks
01/04/2016	01/04/2016	TM02	TM02 Cross Level Out Of Calibration
01/04/2016	02/04/2016	TM02	48W Elec Svce TM02
02/04/2016	02/04/2016	TM02	TM02 horn not loud enough
03/04/2016	03/04/2016	TM02	TM02 Replace Fire Suppression parts *SES
03/04/2016	03/04/2016	TM02	1Y Stat Insp Portable Fire Extg TM02 *SE
03/04/2016	07/04/2016	TM02	6M Stat Insp Fire Supp Track Mach TM02*S
07/04/2016	07/04/2016	TM02	3M Stat Test DB TM02
08/04/2016	08/04/2016	TM02	6M Stat Test Fixed RCD Button TM02
15/04/2016	15/04/2016	TM02	TM02 Inner tynes are worn.
15/04/2016	15/04/2016	TM02	TM02 Rear cab window wiper at fault
15/05/2016	15/05/2016	TM02	TM02 cracked air line
18/06/2016	18/06/2016	TM02	12W Elec Svce TM02
18/06/2016	18/06/2016	TM02	12W Mech Svce TM02
19/06/2016	19/06/2016	TM02	TM02 Replace W/Head 3 Squeeze flap
23/06/2016	23/06/2016	TM02	TM02 Replace Brake Shoes
01/07/2016	01/07/2016	TM02	3M Stat Insp TM02 Test & Tag
01/07/2016	01/07/2016	TM02	3M Stat Insp TM02 Generator
01/07/2016	01/07/2016	TM02	3M Stat Insp TM02 E-Stops
01/07/2016	01/07/2016	TM02	3M Stat Test Welder TM02
02/07/2016	02/07/2016	TM02	TM02 BRAKE SYSTEM OVERHAUL
02/07/2016	02/07/2016	TM02	TM02 Assist maint with brake repairs
07/07/2016	07/07/2016	TM02	3M Stat Test DB TM02
18/07/2016	18/07/2016	TM02	TM02 Generator Batteries Flat
25/07/2016	25/07/2016	TM02	TM02 Replaced Lifting Unit Proxy
25/07/2016	25/07/2016	TM02	TM02 - REBUILD LIFT CYLINDER & RTW
28/07/2016	28/07/2016	TM02	TM02 Complete brake test/risk assessment
15/08/2016	17/08/2016	TM02	TM02 - Plasser Static Testing RSM W/S
16/08/2016	16/08/2016	TM02	TM02 DGPS tablet install & commissioning
08/09/2016	08/09/2016	TM02	TM02 Throttle not working
10/09/2016	10/09/2016	TM02	12W Elec Svce TM02
10/09/2016	11/09/2016	TM02	24W Mech Svce TM02
10/09/2016	10/09/2016	TM02	12W Elec Svce TM02
10/09/2016	10/09/2016	TM02	48W Sfty Insp Pressure Vessel TM02
11/09/2016	12/09/2016	TM02	24W Mech Svce TM02
11/09/2016	11/09/2016	TM02	1Y Sfty Insp Trauma Kit TM02
12/09/2016	12/09/2016	TM02	TM02 Fit RCD test points
12/09/2016	12/09/2016	TM02	TM02 Reseal Workhead split cylinder
12/09/2016	12/09/2016	TM02	TM02 Pivot seals require overhaul
12/09/2016	12/09/2016	TM02	TM02 Broken tyne in RHS
12/09/2016	12/09/2016	TM02	TM02 Return Filter needs new O-ring
12/09/2016	12/09/2016	TM02	TM02 L/H/F outter Pivot Cylinder Leak
12/09/2016	12/09/2016	TM02	TM02 PLC Cabinet hinge bolts missing
13/09/2016	13/09/2016	TM02	TM02 Vibration from tamping tyne
14/09/2016	14/09/2016	TM02	TM02 Bogie Support Cylinders Leaking RTW

14/09/2016	14/09/2016	TM02	TM02 Trailer roof is loose.
15/09/2016	15/09/2016	TM02	6M Stat Insp Portable Fire Extg TM02 *SE
15/09/2016	15/09/2016	TM02	1Y Stat Insp Fire Supp Track Mach TM02 *
17/09/2016	17/09/2016	TM02	TM02 cylinders on roof.*SES*
18/09/2016	18/09/2016	TM02	TM02 - 3 X L/H WHEEL SUPPORT CYL U/S
18/09/2016	18/09/2016	TM02	TM02 L/H Front Cab Support
27/09/2016	27/09/2016	TM02	3M Stat Test DB TM02
02/10/2016	02/10/2016	TM02	3M Stat Insp TM02 Test & Tag
02/10/2016	02/10/2016	TM02	3M Stat Insp TM02 Generator
02/10/2016	02/10/2016	TM02	3M Stat Insp TM02 E-Stops
02/10/2016	02/10/2016	TM02	3M Stat Test Welder TM02
02/10/2016	02/10/2016	TM02	6M Stat Test Fixed RCD Button TM02
02/10/2016	02/10/2016	TM02	3M Stat Test DB TM02
10/10/2016	10/10/2016	TM02	TM02- BRAKE BOOSTERS NEED
12/10/2016	12/10/2016	TM02	1Y Stat Test Fixed RCD Injection TM02
12/10/2016	12/10/2016	TM02	1Y Stat Insp Safety Signs TM02
12/10/2016	12/10/2016	TM02	1Y Sfty Insp Guarding & Handrails TM02
19/10/2016	19/10/2016	TM02	Complete 3M Stat Test Welder TM02
21/10/2016	21/10/2016	TM02	TM02 Lining roller on lift unit broken
13/11/2016	13/11/2016	TM02	TM02 Work Heads Frames *SES*
22/11/2016	22/11/2016	TM02	TM02 Brake function test
29/11/2016	03/12/2016	TM02	250H Mech & Elec Svce TM02
04/12/2016	07/12/2016	TM02	192W Mech Ovhl Work Head TM02
04/12/2016	05/12/2016	TM02	2Y Stat Insp Earthing Systems TM02
04/12/2016	04/12/2016	TM02	TM02 Workhead split and auto line
05/12/2016	05/12/2016	TM02	TM02 genset fuel line leaking
06/12/2016	11/12/2016	TM02	TM02 - DAMAGED SWIVEL TYNE HOUSING GR
06/12/2016	06/12/2016	TM02	TM02 WH Outer Extension Cyl Control Valv
07/12/2016	07/12/2016	TM02	TM02 Replace throttle actuator
07/12/2016	07/12/2016	TM02	TM02 Replace Light Fittings
08/12/2016	08/12/2016	TM02	TM02 rear cab door locks itself
08/12/2016	08/12/2016	TM02	48W Tech Svce AC TM02 SES
09/12/2016	09/12/2016	TM02	TM02 WH Squeeze flaps RHR inner & outer
10/12/2016	10/12/2016	TM02	TM02 Tyne Swivel Cyl LHF outer
10/12/2016	11/12/2016	TM02	TM02 Fit inline fuses to RCD selector sw
11/12/2016	11/12/2016	TM02	TM02 WH Lift Cyl LH outer
12/12/2016	12/12/2016	TM02	TM02 Left Auto Position not working
12/12/2016	12/12/2016	TM02	TM02 Lift calibration
12/12/2016	12/12/2016	TM02	TM02 ALC repeatedly stoping to count
29/12/2016	29/12/2016	TM02	3M Stat Test DB TM02
29/12/2016	29/12/2016	TM02	3M Stat Insp Test & Tag TM02
29/12/2016	29/12/2016	TM02	3M Stat Insp Generator TM02
29/12/2016	29/12/2016	TM02	3M Stat Insp E-Stops TM02
29/12/2016	29/12/2016	TM02	6M Stat Test Fixed RCD Button TM02
29/12/2016	29/12/2016	TM02	3M Stat Test Welder TM02
09/01/2017	10/01/2017	TM02	PTO TM02 WorkHead C/O WIN Request
01/02/2017	21/06/2017	TM02	ACT Create TL TM02 Head C/O M.Wojas
02/02/2017	07/06/2017	TM02	ACT Create PMI TM02 Head C/O M.Wojas
22/02/2017	22/02/2017	TM02	TM02 Air Horn Not Loud Enough

25/02/2017	25/02/2017	TM02	TM02 Work Head #1 R/Hand Outer Hook lock
25/02/2017	01/03/2017	TM02	4000H Mech & Elec Svce TM02 - RTW
25/02/2017	25/02/2017	TM02	48W Comm Tech Insp Radio TM02
25/02/2017	25/02/2017	TM02	TM02 Rebuilt workhead tyne holders fault
27/02/2017	27/02/2017	TM02	TM02 ZF Trans leaks from wiring connecti
27/02/2017	27/02/2017	TM02	TM02 Compressor leaks
27/02/2017	27/02/2017	TM02	HAZ - Danger Signage Fallen Off TM02
27/02/2017	27/02/2017	TM02	TM02 Rear Cab Door Lock
28/02/2017	28/02/2017	TM02	TM02 Splitter Box Flange seal leaking
28/02/2017	28/02/2017	TM02	TM02 rear washer bottle pump wires
28/02/2017	28/02/2017	TM02	TM02 gauge to secure
01/03/2017	01/03/2017	TM02	TM02 Workhead Flow Dividers leaking
01/03/2017	27/05/2017	TM02	TM02 Flap cylinders LH inner rear and RH
03/03/2017	03/03/2017	TM02	1Y Stat Insp Portable Fire Extg TM02
03/03/2017	03/03/2017	TM02	6M Stat Insp Fire Supp Track Mach TM02
04/03/2017	04/03/2017	TM02	TM02 Handrails have middle rail
04/03/2017	04/03/2017	TM02	TM02 Check for recalled circuit breaker.
05/03/2017	05/03/2017	TM02	TM02 - RESEAL SWIVEL CYLINDER (SPARE)
14/03/2017	14/03/2017	TM02	TM02 Head Split Lock Cyl Knuckle Brocken
14/03/2017	14/03/2017	TM02	TM02 Rear Cab door Lock Needs Modifying
15/03/2017	15/03/2017	TM02	TM02 Main Engine Fan Belts Loose
31/03/2017	31/03/2017	TM02	3M Stat Test DB TM02
31/03/2017	31/03/2017	TM02	3M Stat Insp Test & Tag TM02
31/03/2017	31/03/2017	TM02	3M Stat Insp Generator TM02
01/04/2017	01/04/2017	TM02	3M Stat Insp E-Stops TM02
01/04/2017	01/04/2017	TM02	3M Stat Test Welder TM02
17/04/2017	17/04/2017	TM02	Intall Lable TM02-B
21/04/2017	21/04/2017	TM02	TM02 damaged versine carrier fork
21/04/2017	21/04/2017	TM02	TM02 B-Point Not Referencing
26/04/2017	26/04/2017	TM02	TM02 #3 work head elect fault
28/04/2017	28/04/2017	TM02	TM02 front pendulum electrical fault
13/05/2017	13/05/2017	TM02	TM03 Lining roller rebuild
20/05/2017	20/05/2017	TM02	TM02 Fire Extinguisher relocation**NCD**
20/05/2017	20/05/2017	TM02	TM02 Front cab Door seal damaged
22/05/2017	22/05/2017	TM02	TM02 hand tamper storage
22/05/2017	22/05/2017	TM02	TM02 PLC battery to replace
23/05/2017	27/05/2017	TM02	250H Mech & Elec Svce TM02
24/05/2017	24/05/2017	TM02	TM02 Tyne swivel Cylinders Leaking
27/05/2017	27/05/2017	TM02	TM02 - SPLITTER BOX LEAK
27/05/2017	27/05/2017	TM02	TM02 - REPLACE SWIVEL CYL HOSES
21/06/2017	21/06/2017	TM02	TM02 faulty Plc card
04/07/2017	04/07/2017	TM02	3M Stat Test DB TM02
04/07/2017	04/07/2017	TM02	3M Stat Insp Test & Tag TM02
05/07/2017	05/07/2017	TM02	3M Stat Insp Generator TM02
05/07/2017	05/07/2017	TM02	3M Stat Insp E-Stops TM02
12/07/2017	12/07/2017	TM02	TM02 needs new shock absorbers
12/07/2017	12/07/2017	TM02	TM02 Hatz Genset Not Statring
14/07/2017	14/07/2017	TM02	1Y Stat Test Fixed RCD Button & Inj TM02
23/07/2017	23/07/2017	TM02	TM02 Condition report and OEM Audit **se

26/07/2017	26/07/2017 TM02	3M Stat Test Welder TM02
10/08/2017	13/08/2017 TM02	500H Mech & Elec Svce TM02
12/08/2017	12/08/2017 TM02	1Y Sfty Insp Pressure Vessel TM02
12/08/2017	12/08/2017 TM02	1Y Sfty Insp Guarding & Handrails TM02
12/08/2017	12/08/2017 TM02	1Y Stat Insp Safety Signs TM02
12/08/2017	12/08/2017 TM02	1Y Sfty Insp Trauma Kit TM02
14/08/2017	14/08/2017 TM02	TM02 encoder not working
14/08/2017	14/08/2017 TM02	TM02 Workhead In And Out Cylinder
14/08/2017	18/08/2017 TM02	TM02 Tamping Head Sliding Cylinder
14/08/2017	14/08/2017 TM02	O/S - TM02 Scope Machine for Repairs
14/08/2017	14/08/2017 TM02	TM02 E-stop contacts corroded.
15/08/2017	15/08/2017 TM02	TM02 TYNE SWIVEL SEALS REPLACE
15/08/2017	15/08/2017 TM02	TM02 Retest Class 1 Appliances
16/08/2017	16/08/2017 TM02	TM02 Rear Wiper Not Working
16/08/2017	16/08/2017 TM02	TM02 Hyd Pump RH Hose Connect
16/08/2017	16/08/2017 TM02	TM02 Leaking work head flow divider
16/08/2017	16/08/2017 TM02	TM02 labelling in cab
16/08/2017	16/08/2017 TM02	TM02 - REPLACE SWIVEL CYLINDER
16/08/2017	16/08/2017 TM02	TM02 - INTER DRIVE SHAFT PLUGS
17/08/2017	17/08/2017 TM02	TM02 Replace Hatz alternator
17/08/2017	17/08/2017 TM02	6M Stat Insp Portable Fire Extg TM02
17/08/2017	17/08/2017 TM02	1Y Stat Insp Fire Supp Track Mach TM02
17/08/2017	17/08/2017 TM02	TM02 Hydraulic Leaks Above WorkHeads
18/08/2017	18/08/2017 TM02	TM02 - SPLITTER BOX TUBE C/O
18/08/2017	18/08/2017 TM02	TM02 breaker to be changed.
18/08/2017	04/09/2017 TM02	TM02 fridge door seals perished
18/08/2017	18/08/2017 TM02	TM02 Oil Leak On Eng Air Compressor
20/08/2017	20/08/2017 TM02	TM02 Main Engine Belts Loose
21/08/2017	22/08/2017 TM02	TM02 work pendulum error Hi rail
08/09/2017	08/09/2017 TM02	TM02 LH Flow Divider leaking
12/09/2017	12/09/2017 TM02	Tamper 2 maintenace/ consumables
15/09/2017	15/09/2017 TM02	TM02 LHS Cord Tension Not Working
22/09/2017	22/09/2017 TM02	O/S TM02 hatz wiring frayed
24/09/2017	24/09/2017 TM02	Travel TM02 Newman to Kurrajurra 24/9
26/09/2017	26/09/2017 TM02	TM02 Left Hand Work Head Lock Broken
27/09/2017	27/09/2017 TM02	3M Stat Test DB TM02
27/09/2017	27/09/2017 TM02	3M Stat Insp Test & Tag TM02
27/09/2017	27/09/2017 TM02	3M Stat Insp Generator TM02
28/09/2017	28/09/2017 TM02	3M Stat Insp E-Stops TM02
28/09/2017	28/09/2017 TM02	3M Stat Test Welder TM02
29/09/2017	29/09/2017 TM02	PTO 4000H Elec Svce Tampers 0119162
04/11/2017	04/11/2017 TM02	TM02 - PRESSURE CLEAN MACHINE
15/12/2017	15/12/2017 TM02	TM02 Axel 2 Quick Exhaust Valve
26/12/2017	27/12/2017 TM02	Travel Tamper 2 to Workshop 22/12/17
27/12/2017	27/12/2017 TM02	3M Stat Test Welder TM02
27/12/2017	27/12/2017 TM02	TM02 Electrical Alarm For Lock Indicator
27/12/2017	27/12/2017 TM02	TM02 Low Brake Pressure
08/01/2018	08/01/2018 TM02	3M Stat Test DB TM02
08/01/2018	08/01/2018 TM02	3M Stat Insp Test & Tag TM02

08/01/2018	08/01/2018	TM02	3M Stat Insp Generator TM02
08/01/2018	08/01/2018	TM02	3M Stat Insp E-Stops TM02
08/01/2018	08/01/2018	TM02	6M Stat Test Fixed RCD Button TM02
27/01/2018	27/01/2018	TM02	1Y Stat Insp Portable Fire Extg TM02
27/01/2018	28/01/2018	TM02	1000H Mech & Elec Svce TM02
28/01/2018	28/01/2018	TM02	TM02 Fit Tamper Proof tape to fire suppr
28/01/2018	28/01/2018	TM02	6M Stat Insp Fire Supp Track Mach TM02
29/01/2018	29/01/2018	TM02	TM02 new fridge
30/01/2018	30/01/2018	TM02	250H Mech & Elec Svce TM02
04/02/2018	04/02/2018	TM02	1Y Stat Recert Defibrillator TM02
09/02/2018	16/02/2018	TM02	TM02 alarm on drive mode
18/02/2018	18/02/2018	TM02	O/S - TM02 E-stop Labels Faded
18/03/2018	18/03/2018	TM02	48W Tech Svce AC TM02
28/03/2018	28/03/2018	TM02	3M Stat Insp Generator TM02
29/03/2018	29/03/2018	TM02	3M Stat Insp Test & Tag TM02
29/03/2018	29/03/2018	TM02	3M Stat Insp E-Stops TM02
03/04/2018	03/04/2018	TM02	3M Stat Test DB TM02
04/04/2018	04/04/2018	TM02	48W Comm Tech Insp Radio TM02
21/04/2018	21/04/2018	TM02	250H Mech & Elec Svce TM02
22/04/2018	22/04/2018	TM02	TM02 Fuel Transfer Pump Sticking
23/04/2018	23/04/2018	TM02	TM02 replace lock detection relay board
27/06/2018	27/06/2018	TM02	3M Stat Test DB TM02
27/06/2018	27/06/2018	TM02	3M Stat Insp Test & Tag TM02
27/06/2018	27/06/2018	TM02	3M Stat Insp Generator TM02
27/06/2018	27/06/2018	TM02	3M Stat Insp E-Stops TM02
10/07/2018	10/07/2018	TM02	6M Stat Insp Portable Fire Extg TM02
14/07/2018	14/07/2018	TM02	1Y Stat Test Fixed RCD Button & Inj TM02
14/07/2018	14/07/2018	TM02	1Y Sfty Insp Pressure Vessel TM02
14/07/2018	16/07/2018	TM02	500H Mech & Elec Svce TM02
14/07/2018	14/07/2018	TM02	2Y Stat Insp Earthing Systems TM02
06/09/2018	07/09/2018	TM02	4000H Brake Sys Insp & Dynamic Test TM02
06/11/2018	06/11/2018	TM02	TM02 L/H lifting unit roller clamp
06/11/2018	06/11/2018	TM02	TM02 - Bogie Support Cylinders C/O
06/11/2018	06/11/2018	TM02	TM02 starter solenoid re stock
24/12/2018	24/12/2018	TM02	O/S TM02 Flap Cylinder and Bracket Damag
24/12/2018	24/12/2018	TM02	O/S - TM02 Replace Trailer Brake Blocks
24/12/2018	24/12/2018	TM02	O/S - TM02 Replace LHS Flow Divider
24/12/2018	24/12/2018	TM02	O/S - TM02 Tyne swivel cylinder leaking
24/12/2018	24/12/2018	TM02	O/S - TM02 R/H Levelling Cord Tension Cy
24/12/2018	24/12/2018	TM02	1Y Stat Insp Safety Signs TM02
24/12/2018	24/12/2018	TM02	1Y Sfty Insp Guarding & Handrails TM02
24/12/2018	24/12/2018	TM02	1Y Sfty Insp Trauma Kit TM02
24/12/2018	24/12/2018	TM02	1Y Stat Insp Fire Supp Track Mach TM02
29/12/2018	29/12/2018	TM02	48W Comm Tech Insp Radio TM02
31/12/2018	31/12/2018	TM02	TM02 Replace front brake beam
31/12/2018	31/12/2018	TM02	TM02 Squeeze Cylinders Leaking
31/12/2018	31/12/2018	TM02	TM02 Hyd Pump Connect LH leak
31/12/2018	31/12/2018	TM02	TM02 Work Head Heights Erratic
31/12/2018	31/12/2018	TM02	TM02 Axle 1<(>&<)>2 Quick Release Valve

31/12/2018	31/12/2018 TM02	O/S - TM02 Overhaul Spare Tyne Swivel Cy
31/12/2018	31/12/2018 TM02	TM02 Replace Lock Warning Relays
31/12/2018	03/01/2019 TM02	192W Mech Ovhl Work Head TM02
31/12/2018	31/12/2018 TM02	TM02 Fire Extinguisher Signs Faded o/s
31/12/2018	31/12/2018 TM02	TM02 Engine Bay Light Ballast
31/12/2018	31/12/2018 TM02	TM02 Incorrect Tyne Spacings
31/12/2018	31/12/2018 TM02	TM02 worn brake shoes
31/12/2018	31/12/2018 TM02	TM02 Rear X Level Display Not Working
31/12/2018	31/12/2018 TM02	TM02 Wing Mirror RH Front cab
31/12/2018	31/12/2018 TM02	TM02 Tyne swivel cyl pin
31/12/2018	31/12/2018 TM02	TM02 Reterminate Potentiometer Plugs

Description

Lifting & Lining Unit TM02
Air System Components TM02
Tamping System TM02
Hydraulic Components TM02
Lining Measurement System TM02
Tamper TM02
Lining Measurement System TM02
Engine Top & Bottom End TM02
Tamping System TM02
Hydraulic Components TM02
Hydraulic Components TM02
Lifting & Lining Unit TM02
Engine Top & Bottom End TM02
Tamper TM02
Tamper TM02
Tamper TM02
Engine Top & Bottom End TM02
Air System Components TM02
Inst Wiring & Lights TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Cooling System Engine TM02
Tamping System TM02
Induction & Exhaust System TM02
Cooling System Engine TM02
Cooling System Engine TM02
Lifting & Lining Unit TM02
Tamping System TM02
Tamper TM02
Tamper TM02
Tamper TM02
Air System Components TM02
Tamper TM02
Transmission TM02
Drive TM02
Tamper TM02
Fuel System TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Implements & Attachments TM02
Tamper TM02
Tamper TM02

Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Inst Wiring & Lights TM02
Inst Wiring & Lights TM02
Drive Hydraulic TM02
Tamper TM02
Tamper TM02
Hydraulic Components TM02
Comms & Controls TM02
Protection Devices TM02
Hydraulic Components TM02
Brake Components TM02
Tamping System TM02
Cooling System Engine TM02
Levelling System TM02
Cooling System Engine TM02
Air System Components TM02
Brake Components TM02
Hydraulic Components TM02
Starting & Charging TM02
Comms & Controls TM02
Comms & Controls TM02
Tamper TM02
Cooling System Engine TM02
Elec Inst & Controls TM02
Tamper TM02
Lifting & Lining Unit TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Brake Pneumatic TM02
Tamper TM02
Operators Cabin TM02
Starting & Charging TM02
Tamper TM02
Tamper TM02
Tamper TM02
Inst Wiring & Lights TM02
Tamper TM02
Lining Measurement System TM02
Hydraulic Components TM02
Comms & Controls TM02
Hydraulic Components TM02
Drive Hydraulic TM02
Hydraulic Components TM02

Alternator or Generator TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Inst Wiring & Lights TM02
Inst Wiring & Lights TM02
Hydraulic Components TM02
Drive TM02
Drive TM02
Transmission TM02
Frame & Chassis TM02
Tamper TM02
Inst Wiring & Lights TM02
Engine TM02
Inst Wiring & Lights TM02
Hydraulic Components TM02
Comms & Controls TM02
Comms & Controls TM02
Air System Components TM02
Tamper TM02
Hydraulic Components TM02
Tamper TM02
Elec Inst & Controls TM02
Lifting & Lining Unit TM02
Operators Cabin TM02
Tamper TM02
Hydraulic Components TM02
Tamper TM02
Air System Components TM02
Brake Components TM02
Tamper TM02
Tamper TM02
Tamping System TM02
Hydraulic Components TM02
Frame & Chassis TM02
Inst Wiring & Lights TM02
Elec Inst & Controls TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Frame & Chassis TM02
Comms & Controls TM02
Elec Inst & Controls TM02

Tamper TM02
Cooling System Hydraulic TM02
Hydraulic Components TM02
Tamper TM02
Protection Devices TM02
Protection Devices TM02
Tamper TM02
Tamper TM02
Brake Pneumatic TM02
Air System Components TM02
Starting & Charging TM02
Tamper TM02
Compressor TM02
Transmission TM02
Levelling System TM02
Lining Measurement System TM02
Tamper TM02
Air System Components TM02
Brake Pneumatic TM02
Air System Components TM02
Elec Inst & Controls TM02
Inst Wiring & Lights TM02
Tamper TM02
Hydraulic Components TM02
Tamper TM02
Tamper TM02
Bogies TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Hydraulic Components TM02
Inst Wiring & Lights TM02
Tamper TM02
Tamper TM02
Elec Inst & Controls TM02
Hydraulic Components TM02
Tamper TM02
Hydraulic Components TM02
Tamper TM02
Tamper TM02
Tamper TM02
Elec Inst & Controls TM02
Comms & Controls TM02
Air System Components TM02
Tamper TM02
Tamper TM02

Tamper TM02
Protection Devices TM02
Protection Devices TM02
Comms & Controls TM02
Inst Wiring & Lights TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Air System Components TM02
Elec Inst & Controls TM02
Tamping System TM02
Tamping System TM02
Induction & Exhaust System TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Hydraulic Components TM02
Tamper TM02
Tamper TM02
Frame & Chassis TM02
Protection Devices TM02
Starting & Charging TM02
Lifting & Lining Unit TM02
Lining Measurement System TM02
Protection Devices TM02
Tamper TM02
Tamper TM02
Pneumatic System TM02
Operators Cabin TM02
Tamper TM02
Tamper TM02
Elec Inst & Controls TM02
Lifting & Lining Unit TM02
Air System Components TM02
Tamper TM02
Hydraulic Components TM02
Frame & Chassis TM02
Tamper TM02
Engine TM02
Tamper TM02
Tamper TM02
Tamper TM02
Starting & Charging TM02

[illegible]

Inst Wiring & Lights TM02
Tamper TM02
Hydraulic System TM02
Drive TM02
Alternator or Generator TM02
Brake Pneumatic TM02
Brake Pneumatic TM02
Hydraulic System TM02
Frame & Chassis TM02
Operators Cabin TM02
Inst Wiring & Lights TM02
Air System Components TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Comms & Controls TM02
Elec Inst & Controls TM02
Tamper TM02
Starting & Charging TM02
Cooling System Engine TM02
Lifting & Lining Unit TM02
Air System Components TM02
Air System Components TM02
Tamping System TM02
Tamper TM02
Hydraulic Components TM02
Tamper TM02
Comms & Controls TM02
Operators Cabin TM02
Inst Wiring & Lights TM02
Hydraulic System TM02
Frame & Chassis TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Lifting & Lining Unit TM02
Hydraulic Components TM02
Tamping System TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Comms & Controls TM02
Protection Devices TM02
Air System Components TM02
Engine TM02

[illegible]

Frame & Chassis TM02
Structure TM02
Hydraulic System TM02
Tamper TM02
Engine Top & Bottom End TM02
Hydraulic Components TM02
Tamping System TM02
Hydraulic System TM02
Lifting & Lining Unit TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamping System TM02
Tamper TM02
Tamper TM02
Hydraulic Components TM02
Tamper TM02
Tamper TM02
Inst Wiring & Lights TM02
Tamper TM02
Tamper TM02
Tamper TM02
Cooling System Hydraulic TM02
Tamper TM02
Protection Devices TM02
Tamper TM02
Elec Inst & Controls TM02
Frame & Chassis TM02
Frame & Chassis TM02
Tamper TM02
Air System Components TM02
Levelling System TM02
Air System Components TM02
Tamper TM02
Tamper TM02
Tamper TM02
Lifting & Lining Unit TM02
Compressor TM02
Tamper TM02
Tamper TM02
Tamper TM02
Operators Cabin TM02
Operators Cabin TM02
Levelling System TM02
Frame & Chassis TM02
Comms & Controls TM02
Tamper TM02
Lifting & Lining Unit TM02

Tamper TM02
Cooling System Engine TM02
Tamper TM02
Tamper TM02
Tamper TM02
Levelling System TM02
Tamper TM02
Inst Wiring & Lights TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Operators Cabin TM02
Air System Components TM02
Tamper TM02
Tamper TM02
Tamper TM02
Brake Pneumatic TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Brake Pneumatic TM02
Brake Pneumatic TM02
Tamper TM02
Starting & Charging TM02
Protection Devices TM02
Hydraulic Components TM02
Brake Components TM02
Tamper TM02
Tamper TM02
Comms & Controls TM02
Tamper TM02
Tamper TM02
Tamper TM02
Pneumatic System TM02
Tamper TM02
Tamper TM02
Protection Devices TM02
Tamper TM02
Tamping System TM02
Tamping System TM02
Hydraulic Components TM02
Hydraulic Components TM02
Comms & Controls TM02
Hydraulic Components TM02
Tamper TM02

Frame & Chassis TM02
Tamper TM02
Tamper TM02
Hydraulic Components TM02
Hydraulic Components TM02
Hydraulic Components TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Brake Pneumatic TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Lifting & Lining Unit TM02
Tamping System TM02
Brake Pneumatic TM02
Tamper TM02
Tamping System TM02
Tamper TM02
Comms & Controls TM02
Alternator or Generator TM02
Tamping System TM02
Hydraulic Components TM02
Comms & Controls TM02
Inst Wiring & Lights TM02
Operators Cabin TM02
Tamper TM02
Tamping System TM02
Tamping System TM02
Protection Devices TM02
Tamping System TM02
Comms & Controls TM02
Levelling System TM02
Levelling System TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamping System TM02
Tamping System TM02
Tamping System TM02
Air System Components TM02

Tamping System TM02
Tamper TM02
Tamper TM02
Implements & Attachments TM02
Transmission TM02
Compressor TM02
Tamper TM02
Operators Cabin TM02
Transmission TM02
Inst Wiring & Lights TM02
Inst Wiring & Lights TM02
Hydraulic Components TM02
Tamping System TM02
Tamper TM02
Tamper TM02
Operators Cabin TM02
Inst Wiring & Lights TM02
Tamping System TM02
Tamping System TM02
Operators Cabin TM02
Engine TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Protection Devices TM02
Comms & Controls TM02
Air System Components TM02
Lifting & Lining Unit TM02
Comms & Controls TM02
Lifting & Lining Unit TM02
Frame & Chassis TM02
Operators Cabin TM02
Operators Cabin TM02
Comms & Controls TM02
Tamper TM02
Hydraulic Components TM02
Transmission TM02
Hydraulic Components TM02
Lifting & Lining Unit TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Bogies TM02
Alternator or Generator TM02
Tamper TM02
Tamper TM02

Tamper TM02
Tamper TM02
Pneumatic System TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamping System TM02
Hydraulic Components TM02
Hydraulic Components TM02
Tamper TM02
Tamper TM02
Tamping System TM02
Tamper TM02
Operators Cabin TM02
Hydraulic Components TM02
Hydraulic Components TM02
Tamper TM02
Hydraulic Components TM02
Bogies TM02
Starting & Charging TM02
Tamper TM02
Tamper TM02
Tamper TM02
Transmission TM02
Tamper TM02
Operators Cabin TM02
Tamper TM02
Engine Top & Bottom End TM02
Levelling System TM02
Hydraulic Components TM02
Implements & Attachments TM02
Pneumatic System TM02
Inst Wiring & Lights TM02
Tamper TM02
Air System Components TM02
Tamper TM02
Elec Inst & Controls TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Frame & Chassis TM02
Brake Pneumatic TM02
Tamper TM02
Tamper TM02
Implements & Attachments TM02
Brake Components TM02
Tamper TM02
Elec Inst & Controls TM02

Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Protection Devices TM02
Tamper TM02
Operators Cabin TM02
Tamper TM02
Tamper TM02
Comms & Controls TM02
Tamper TM02
Tamper TM02
Tamper TM02
Elec Inst & Controls TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Fuel System TM02
Elec Inst & Controls TM02
Tamper TM02
Elec Inst & Controls TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Pneumatic System TM02
Tamper TM02
Tamper TM02
Pneumatic System TM02
Lifting & Lining Unit TM02
Bogies TM02
Starting & Charging TM02
Tamping System TM02
Tamper TM02
Hydraulic Components TM02
Hydraulic Components TM02
Air System Components TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Tamper TM02
Brake Pneumatic TM02
Hydraulic Components TM02
Hydraulic Components TM02
Tamping System TM02
Tamper TM02

Hydraulic Components TM02
Tammer TM02
Tamping System TM02
Tammer TM02
Tammer TM02
Tamping System TM02
Brake Components TM02
Lining Measurement System TM02
Operators Cabin TM02
Tamping System TM02
Tammer TM02